

03500.018073

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Jill E. Culler
TETSUYO OHASHI ET AL.)	
	:	Group Art Unit: 2854
Appl. No.: 10/824,400)	
	:	Confirmation No.: 6415
Filed: April 15, 2004)	
	:	
For: BOTH-SIDE RECORDING APPARATUS)	
	:	
U.S. Patent No.: 7,033,014 B2)	
	:	
Issued: April 25, 2006)	August 18, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Lawrence A Stahl/

Lawrence A. Stahl
Attorney for Patentees
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,033,014 B2

DATED : April 25, 2006

INVENTOR(S) : TETSUYO OHASHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE AT ITEM [57] Abstract:

Line 12, "is" should read --are--.

COLUMN 2:

Line 18, "an" should read --a--.

COLUMN 6:

Line 39, "advanced" should read --advances--.

Line 56, "heat" should read --head--.

COLUMN 7:

Line 50, "dusts" should read --dust--.

COLUMN 8:

Line 38, "recoding" should read --recording--.

COLUMN 9:

Line 26, "is" should read --are--.

Line 56, "resulting drawbacks" should read --resulting in drawbacks--.

COLUMN 12:

Line 36, "even it" should read --even if it--.

COLUMN 13:

Line 11, "holes" should read --hole--.

COLUMN 14:

Line 31, "solar **15**," should read --solar--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,033,014 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,033,014 B2

DATED : April 25, 2006

INVENTOR(S) : TETSUYO OHASHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 34:

Line 27, "an" (1st occurrence) should read --a--.

Line 36, "process" should read --processes--.

COLUMN 35:

Line 12, "second" should be deleted.

Line 13, "conveying" should be deleted.

COLUMN 36:

Line 5, "second" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,033,014 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) dc main 250463 v1

